SAFETY DATA SHEET (SDS)

According to 1907/2006/EC, Article 31

DermaRite

May be used to comply with OSHA's Hazard Communication Standard, 29 CFR 1910.1200. Standard must be consulted for specific requirements.

Section I – Identification of the substance/mixture an	d of the comp	any/undertak	ing	
IDENTITY (As Used on Label and List) TOTALBATH	Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.			
Manufacturer's Name DermaRite Industries	Emergency Telephor		0-000	
Address (Number, Street, City, State, and ZIP Code)	Telephone Number for	(973) 56 or Information	9000	
7777 WEST SIDE AVENUE, NORTH BERGEN NJ 07047		(973) 56	9-9000	
Section II – Hazardous identification				
List all hazards regarding the material				
NONE				
List all required label requirement				
NONE				
Recommended use and restriction of use FOR EXTERNAL USE ONLY.				
Section III – Composition/Information on Ingredients				
· · · · · · · · · · · · · · · · · · ·			Other Limits	
Hazardous Components (Specific Chemical Identity; Common Name(s)	OSHA PEL	ACGIH TLV	Recommended	%(optional)
NONE				
Section IV – First aid measures				
Signs and Symptoms of Exposure and Required Treatments NONE				
NONE				
Section V – Fire fighting measures				
Flash Point (Method Used) NONE	Flammable Limits NONE	LEL	UEL	
Extinguishing Media Non-flammable, none necessary				
Special Fire Fighting Procedures				
NONE				
NONE				
Unusual Fire and Explosion Hazards NONE				

(Reproduce locally)

Steps to Be Taken in Case Material Is I		nen hererdeus determent	
Respiratory Protection (Specify Type)	op and water. Waste can be treated as common	non-nazardous detergen	L.
Ventilation	Local Exhaust Not necessary	Special No	
	Mechanical (General)	Other	
	Ok	No	
Protective Gloves	Eye Protection		
Other Protective Clothing or Equipment			
	Normal work clothes.		
Work/Hygienic Practices			
Section VII– Handling ar	nd Storage		
Precautions to Be Taken in Handling a			
	rature and keep in closed containers. Observe n	ormal GMP's.	
		ormal GMP's.	
		ormal GMP's.	
Store at room temper		ormal GMP's.	
Store at room temper		ormal GMP's.	
Store at room temper		ormal GMP's.	
Store at room temper		ormal GMP's.	
Store at room temper		ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	
Incompatibilities Unknown Section VIII – Exposure OSHA's Permissible Exposure Limit NONE Threshold limit values (TLVs) NONE Appropriate engineering controls NONE	ature and keep in closed containers. Observe n	ormal GMP's.	
Store at room temper	ature and keep in closed containers. Observe n	ormal GMP's.	

			Specific Gravity ($H_2O = 1$)	~1.0
Boiling Point		212 °F	Melting Point	N/A
Vapor Density (AIR = 1)	>	·1	Evaporation Rate (Butyl Acetate = 1)	N/A
At 20°C			(Bulyi Acelale = 1)	
Solubility in Water				
Water soluble				
Appearance and Odor				
Light orange viscous	liquid with fragrance.			
Section X – Stability a	nd Reactivity Data			
Stability	Unstable		Conditions to Avoid	
			Avoid freezing	
	Stable	х		
Incompatibility (Materials to Avoid)		^		
	lot soluble with oil pre	enarations		
Hazardous Decomposition or Bypro		cparations		
Trazardous Decomposition of Dyplot	10013			
Hazardous Polymerization	May Occur			
	Will Not Occur	X		

(Reproduce locally)

TOTALBATH- page 3 of 3

Section XI - To	xicological Information		
Route(s) of Entry:	Inhalation?	Skin?	Ingestion?
	NO	NO	YES
Health Hazards (Acute ar	nd Chronic) rritating if placed in eyes, or if i	ngested.	
Carcinogencity:	NTP?	IARC Monographs?	OSHA Regulated?
Signs and Symptoms of E	Exposure		
Medical Conditions	_		
Generally Aggravated by	Exposure		
Emergency and first aid p			
Flush eyes with wa	ater for 15 minutes. If ingested	drink large amounts of water. (Call physician.
	ological Information		
Not applicable			
Section VIII Di	ionacal Canaidaration		
Waste Disposal Method	isposal Consideration		
	ated as a common non-hazardo	us detergent. Flush in drain wit	th plenty of water. Dispose in accordance
With local, state o	or federal regulation.		
Section XIV- Tra	ansport Information		
Not applicable			
Section XV– Re	gulatory Information		
Not applicable			
	they lufermeticn		
Date Prepared	ther Information		
10/04/13			
Signature of Preparer (op	tional)		
- (Reproduce locally)			
		MMENDATIONS IN THIS DATA SHEE	
	CORRECT AND RELIABLE. HO	WEVER THE DATA IS OFFERED FOR	CONSIDERATION AND
		ND DERMARITE INDUSTRIES LLC OF ON AS TO THE ACCURACY OR COM	